



SOUTHWEST SHIPYARD, L.P.
18310 Market Street, Channelview, Texas 77530
Phone: 281-860-3200 Fax: 281-860-3215

F-7.5.1(C).6 - B

BARGE PIPING TEST LETTER

Note: Test Results are valid for One (1) Year from Date of Test !

INSTRUCTIONS: FILL OUT COMPLETELY. WRITE "N/A" ON ANY NON-APPLICABLE LINE.

BARGE NAME/NUMBER: DBL 105

BARGE OWNER: DEVALL

OWNER ADDRESS: 2244 SWisco Bld. Sulphur LA

TESTING LOCATION: SOUTHWEST SHIPYARD, L.C. GAS FRONT CLEANING FACILITY

LETTER EXPIRATION DATE (One Year from Test): 9-19-17

1. **Cargo Piping and Valves (Date of Test):** 9-19-16

Test Pressure (psi): 188 psi

2. **Cargo Pressure Gauge (Date of Test):** 9-19-16

Percent Accuracy (%): 98%

3. **Steam Piping and Valves (Date of Test):** N/A

Test Pressure (psi): N/A

4. **Cargo Tank Relief Valves (Date of Test):** N/A

Test Pressure (psi): N/A

SWSLP Tester/Position: Justin Lindsey / Foreman **Date:** 9-19-16

SWSLP Inspector/Position: LCSB / Supervisor **Date:** 9-19-16

DISTRIBUTION: Place original as last page of "USCG Papers Folder" located in Barge document mailbox.



SOUTHWEST SHIPYARD, L.P.
18310 Market Street, Channelview Texas 77530
Phone 281-860-3200 Fax 281-860-3215

Form # 7.51(C) 19-0

BARGE VAPOR TIGHTNESS DOCUMENT

THE FOLLOWING BARGE WAS TESTED IN ACCORDANCE WITH THE NATIONAL EMISSION STANDARD FOR BENZENE EMISSIONS FROM BENZENE TRANSFER OPERATIONS, 40 CFR – Sub-Chapter C, Part 61, Sub-Part bb, Section 302(e)(2), MARINE VESSEL VAPOR TIGHTNESS REQUIREMENTS.

BARGE NAME/NUMBER: DBL 105

BARGE OWNER: DEVALL

TESTING LOCATION: SOUTHWEST SHIPYARD, L.P.
GAS FRONT OPERATIONS
18310 MARKET STREET
CHANNELVIEW, TX 77530

DATE OF TEST: 9-19-16

SWSLP TESTER / POSITION: JL / FOREMAN

SIGNATURE OF SWSLP TESTER: Just Jimberg

WITNESSING SWSLP INSPECTOR/POSITION: CSB / Supervisor

SWSLP INSPECTOR SIGNATURE: CSB Jon Ross

TEST RESULTS

THIS BARGE HAS BEEN TESTED IN ACCORDANCE WITH 40 CFR PART 60 APPENDIX A-7 TEST METHOD 21 AND IS CONSIDERED VAPOR TIGHT.

TIME START: 11:00

STARTING PRESSURE: 28.0

TIME STOP: 11:30

ENDING PRESSURE: 27.5

LEAK INDICATOR: NO VISUAL LEAK INDICATIONS OBSERVED